


1963 - 64 SPL-310 1500 Wiring Diagram



3 seater, 2 carb, alternator out of green cover service manual